

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.





Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.





Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



● ● ● Current Data

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.






Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.






Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




○ ○ ○ Historic Data

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



● ● ● Current Data

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



●●● Current Data ○○○ Historic Data
— Lowess

Human Health Based Water Supply Chronic Standard 250

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.






Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



● ● ● Current Data


Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



● ● ● Current Data

Aquatic Life Warm Acute Standard 4.2
Aquatic Life Warm Chronic Standard 1.7

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



Agriculture Chronic Standard 100

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.






Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




● ● ● Current Data

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



● ● ● Current Data


Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



* * * Historic Censored Data


Aquatic Life Acute Standard 10,071
Aquatic Life Chronic Standard 1,438

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data


Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



* * * Historic Censored Data


Aquatic Life Acute Standard 5.7
Aquatic Life Chronic Standard 1.2

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




* * * Historic Censored Data

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




* * * Historic Censored Data

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




○ ○ ○ Historic Data

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



* * * Historic Censored Data


Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data


Aquatic Life Acute Standard 49.6
Aquatic Life Chronic Standard 29.3

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




○ ○ ○ Historic Data

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data


Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data

Reach Specific Chronic Standard 1,400


Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



* * * Historic Censored Data


Aquatic Life Acute Standard 281
Aquatic Life Chronic Standard 10.9

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data


Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data


Aquatic Life Acute Standard 4,738
Aquatic Life Chronic Standard 2,618

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




○ ○ ○ Historic Data

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




* * * Historic Censored Data

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data


Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data


Aquatic Life Acute Standard 1,513
Aquatic Life Chronic Standard 168

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data


Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



* * * Historic Censored Data


Aquatic Life Acute Standard 22.0
Aquatic Life Chronic Standard 0.81

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data


Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data


Aquatic Life Acute Standard 564
Aquatic Life Chronic Standard 428

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




○ ○ ○ Historic Data

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



* * * Historic Censored Data


Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data

Aquatic Life Acute Standard 34.0
Aquatic Life Chronic Standard 10.0


Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data

Human Health Based Water Supply Chronic Standard 7.6

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data

Agriculture Chronic Standard 750

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.






Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data

Figure 17. Distribution of selected water-quality constituents relative to time for
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



● ● ● Current Data