Figure 70. Distribution of selected water-quality constituents relative to time for Fountain Creek at East River St. at Pueblo, Co., station 381601104355801.








Figure 70. Distribution of selected water-quality constituents relative to time for Fountain Creek at East River St. at Pueblo, Co., station 381601104355801.






Figure 70. Distribution of selected water-quality constituents relative to time for Fountain Creek at East River St. at Pueblo, Co., station 381601104355801.






Figure 70. Distribution of selected water-quality constituents relative to time for Fountain Creek at East River St. at Pueblo, Co., station 381601104355801.






Figure 70. Distribution of selected water-quality constituents relative to time for Fountain Creek at East River St. at Pueblo, Co., station 381601104355801.






Figure 70. Distribution of selected water-quality constituents relative to time for Fountain Creek at East River St. at Pueblo, Co., station 381601104355801.







Figure 70. Distribution of selected water-quality constituents relative to time for Fountain Creek at East River St. at Pueblo, Co., station 381601104355801.



OOO Historic Data



Figure 70. Distribution of selected water-quality constituents relative to time for Fountain Creek at East River St. at Pueblo, Co., station 381601104355801.







Figure 70. Distribution of selected water-quality constituents relative to time for Fountain Creek at East River St. at Pueblo, Co., station 381601104355801.



OOO Historic Data



Figure 70. Distribution of selected water-quality constituents relative to time for Fountain Creek at East River St. at Pueblo, Co., station 381601104355801.






Figure 70. Distribution of selected water-quality constituents relative to time for Fountain Creek at East River St. at Pueblo, Co., station 381601104355801.






Figure 70. Distribution of selected water-quality constituents relative to time for Fountain Creek at East River St. at Pueblo, Co., station 381601104355801.

