

Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.





Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.



Aquatic Life Standard 6.0

Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.





Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.



Aquatic Life Standard 6.5 to 9.0

Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.





Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.



●●● Current Data, Cool Season Std
○●○ Historic Data, Cool Season Std

●●● Current Data, Warm Season Std
○●○ Historic Data, Warm Season Std

Aquatic Life Jan - Mar, Cool Season Std 13.0
Aquatic Life Apr - Dec, Warm Season Std 23.8

Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.



Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.





Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.



○ ○ ○ Historic Data

Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.





Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.



○ ○ ○ Historic Data

Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.





Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.



Historic Data

Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.





Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.



* * * Historic Censored Data

Aquatic Life Standard 0.05

Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.





Figure 10. Distribution of selected water-quality constituents relative to time for


Olympus Tunnel at Lake Estes Co., station 06734900.



○ ○ ○ Historic Data

Figure 10. Distribution of selected water-quality constituents relative to time for


Olympus Tunnel at Lake Estes Co., station 06734900.



○ ○ ○ Historic Data

Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.



○ ○ ○ Historic Data

Aquatic Life Acute Standard 275
Aquatic Life Chronic Standard 39.2

Olympus Tunnel at Lake Estes Co., station 06734900.




Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.





Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




Olympus Tunnel at Lake Estes Co., station 06734900.



Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.



* * * Historic Censored Data

Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.






Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.



Olympus Tunnel at Lake Estes Co., station 06734900.



Olympus Tunnel at Lake Estes Co., station 06734900.



Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.





Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




○ ○ ○ Historic Data


Aquatic Life Chronic Standard 10.0

Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.



Olympus Tunnel at Lake Estes Co., station 06734900.



USGS
science for a changing world

Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.





Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.



○ ○ ○ Historic Data

Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.





Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




Olympus Tunnel at Lake Estes Co., station 06734900.



Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




★ ★ ★ Historic Censored Data ○ ○ ○ Historic Data

Water and Fish Chronic Standard 2.2

Figure 10. Distribution of selected water-quality constituents relative to time for


Olympus Tunnel at Lake Estes Co., station 06734900.



Water and Fish Chronic Standard 530

Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




* * * Historic Censored Data ○ ○ ○ Historic Data

Human Health Based Water Supply Chronic Standard 1,400

Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.



○ ○ ○ Historic Data

Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.





Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




* * * Historic Censored Data ○ ○ ○ Historic Data

Human Health Based Water Supply Chronic Standard 1,400

Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.




* * * Historic Censored Data ○ ○ ○ Historic Data

Water and Fish Chronic Standard 510

Figure 10. Distribution of selected water-quality constituents relative to time for

Olympus Tunnel at Lake Estes Co., station 06734900.



○ ○ ○ Historic Data