Figure 7. Time distribution and associated discharge of water-quality samples for Fraser River at Tabernash, CO., station 09027100.