



Figure 12. Distribution of selected water-quality constituents relative to time for  
 Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



● ● ● Current Data    ○ ○ ○ Historic Data




Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



● ● ● Current Data    ○ ○ ○ Historic Data

Aquatic Life Standard 5.0


Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



●●● Current Data    ○○○ Historic Data  
— Lowess

Aquatic Life Standard 6.5 to 9.0

Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data

Aquatic Life Standard 6.5 to 9.0

Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




Figure 12. Distribution of selected water-quality constituents relative to time for Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.





Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



● ● ● Current Data, Cool Season Std      ○ ○ ○ Current Data, Warm Season Std  
○ ○ ○ Historic Data, Cool Season Std      ○ ○ ○ Historic Data, Warm Season Std

Aquatic Life Dec - Feb, Cool Season Std 14.3  
 Aquatic Life Mar - Nov, Warm Season Std 28.6

Figure 12. Distribution of selected water-quality constituents relative to time for Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.






Figure 12. Distribution of selected water-quality constituents relative to time for Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




Figure 12. Distribution of selected water-quality constituents relative to time for Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.





Figure 12. Distribution of selected water-quality constituents relative to time for Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



●●● Current Data    ○○○ Historic Data  
— Lowess

Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




Figure 12. Distribution of selected water-quality constituents relative to time for

Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.





Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data



Figure 12. Distribution of selected water-quality constituents relative to time for Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.






Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data

Figure 12. Distribution of selected water-quality constituents relative to time for Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




●●● Current Data    ○○○ Historic Data  
— Lowess






Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



●●● Current Data    ○○○ Historic Data  
— Lowess

Figure 12. Distribution of selected water-quality constituents relative to time for Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



●●● Current Data    ○○○ Historic Data  
— Lowess

Water Supply Chronic Standard 250



Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.






Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



\* \* \* Current Censored Data      ● ● ● Current Data  
\* \* \* Historic Censored Data      ○ ○ ○ Historic Data  
— Lowess

Aquatic Life Warm Acute Standard 4.5  
 Aquatic Life Warm Chronic Standard 1.9

Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




●●● Current Data    ○○○ Historic Data  
— Lowess

Agriculture Acute Standard 10.0




Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



●●● Current Data    ○○○ Historic Data  
— Lowess


Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



●●● Current Data    ○○○ Historic Data  
— Lowess

Aquatic Life Chronic Standard 0.17


Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



\* \* \* Historic Censored Data

Aquatic Life Acute Standard 10,071  
Aquatic Life Chronic Standard 1,438


Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data




Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



\* \* \* Historic Censored Data


Aquatic Life Acute Standard 10.0  
Aquatic Life Chronic Standard 2.0

Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




\* \* \* Historic Censored Data

Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




\* \* \* Historic Censored Data

Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




○ ○ ○ Historic Data

Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



\* \* \* Historic Censored Data


Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data


Aquatic Life Acute Standard 49.6  
Aquatic Life Chronic Standard 29.3

Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data

Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




○ ○ ○ Historic Data

Human Health Based Water Supply Chronic Standard 300




Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data

Reach Specific Chronic Standard 1,400


Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



\* \* \* Historic Censored Data


Aquatic Life Acute Standard 281  
Aquatic Life Chronic Standard 10.9

Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data


Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data


Aquatic Life Acute Standard 4,738  
Aquatic Life Chronic Standard 2,618

Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




○ ○ ○ Historic Data

Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




\* \* \* Historic Censored Data

Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data

Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




○ ○ ○ Historic Data

Aquatic Life Acute Standard 1,513  
Aquatic Life Chronic Standard 168




Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data


Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



\* \* \* Historic Censored Data


Aquatic Life Acute Standard 22.0  
Aquatic Life Chronic Standard 3.5

Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data


Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data


Aquatic Life Acute Standard 564  
Aquatic Life Chronic Standard 428

Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




○ ○ ○ Historic Data

Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



\* \* \* Historic Censored Data


Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data

Aquatic Life Acute Standard 340

Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




○ ○ ○ Historic Data

Human Health Based Water Supply Chronic Standard 0.020



Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data

Agriculture Chronic Standard 750

Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.




Figure 12. Distribution of selected water-quality constituents relative to time for

Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.





Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.



○ ○ ○ Historic Data

Figure 12. Distribution of selected water-quality constituents relative to time for  
Loutsenhizer Arroyo below North River Road near Delta, CO, station 383946107595301.

