

Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.





Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.



Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.



● ● ● Current Data

Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.





Figure 14. Distribution of selected water-quality constituents relative to time for


Montrose Arroyo at East Niagara Street, station 382802107513301.



○ ○ ○ Historic Data

Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.



○ ○ ○ Historic Data

Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.





Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.



○ ○ ○ Historic Data

Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.





Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.



● ● ● Current Data * * * Historic Censored Data
○ ○ ○ Historic Data — Lowess

Human Health Based Water Supply Chronic Standard 2.0

Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.





Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.



● ● ● Current Data
○ ○ ○ Historic Data
* * * Historic Censored Data
— Lowess

Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.





Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




● ● ● Current Data ○ ○ ○ Historic Data

Aquatic Life Warm Acute Standard 4.7
Aquatic Life Warm Chronic Standard 2.0

Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.



Agriculture Chronic Standard 100

Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.





Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.



* * * Current Censored Data ● ● ● Current Data
* * * Historic Censored Data ○ ○ ○ Historic Data

Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.





Figure 14. Distribution of selected water-quality constituents relative to time for


Montrose Arroyo at East Niagara Street, station 382802107513301.



Historic Data

Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




* * * Historic Censored Data

Aquatic Life Acute Standard 5.7
Aquatic Life Chronic Standard 1.2

Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




○ ○ ○ Historic Data

Aquatic Life Acute Standard 49.6
Aquatic Life Chronic Standard 29.3

Figure 14. Distribution of selected water-quality constituents relative to time for


Montrose Arroyo at East Niagara Street, station 382802107513301.



○ ○ ○ Historic Data

Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




* * * Historic Censored Data

Aquatic Life Acute Standard 281
Aquatic Life Chronic Standard 10.9

Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




○ ○ ○ Historic Data

Aquatic Life Acute Standard 4,738
Aquatic Life Chronic Standard 2,618

Figure 14. Distribution of selected water-quality constituents relative to time for


Montrose Arroyo at East Niagara Street, station 382802107513301.



○ ○ ○ Historic Data

Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




* * * Historic Censored Data

Aquatic Life Acute Standard 564
Aquatic Life Chronic Standard 428

Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




* * * Historic Censored Data

Aquatic Life Acute Standard 340
Aquatic Life Chronic Standard 10.0

Figure 14. Distribution of selected water-quality constituents relative to time for


Montrose Arroyo at East Niagara Street, station 382802107513301.



○ ○ ○ Historic Data

Figure 14. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.



● ● ● Current Data