



Figure 7. Time distribution and associated discharge of water-quality samples for Uncompahgre River at Colona, CO, station 09147500.



Duration curve based on 50 years of data      Current water-quality sample