

Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.





Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.



Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




● ● ● Current Data ○ ○ ○ Historic Data
— Lowess

Aquatic Life Standard 6.5 to 9.0

Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.



○ ○ ○ Historic Data — Lowess

Aquatic Life Standard 6.5 to 9.0

Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.



Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.



Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.





Figure 9. Distribution of selected water-quality constituents relative to time for


Montrose Arroyo at East Niagara Street, station 382802107513301.



○ ○ ○ Historic Data

Figure 9. Distribution of selected water-quality constituents relative to time for


Montrose Arroyo at East Niagara Street, station 382802107513301.



● ● ● Current Data ○ ○ ○ Historic Data
— Lowess

Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.



○ ○ ○ Historic Data

Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.





Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.



Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




● ● ● Current Data
○ ○ ○ Historic Data

* * * Historic Censored Data
— Lowess

Water Supply Chronic Standard 250

Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




●●● Current Data ○○○ Historic Data
— Lowess

Aquatic Life Warm Acute Standard 4.9
Aquatic Life Warm Chronic Standard 2.1

Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




●●● Current Data ○○○ Historic Data
— Lowess

Aquatic Life Acute Standard 0.050

Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




●●● Current Data ○○○ Historic Data
— Lowess

Aquatic Life Chronic Standard 0.17

Figure 9. Distribution of selected water-quality constituents relative to time for


Montrose Arroyo at East Niagara Street, station 382802107513301.



○ ○ ○ Historic Data

Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




* * * Historic Censored Data

Aquatic Life Acute Standard 10.0
Aquatic Life Chronic Standard 2.0

Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




○ ○ ○ Historic Data

Aquatic Life Acute Standard 49.6
Aquatic Life Chronic Standard 29.3

Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




○ ○ ○ Historic Data

Human Health Based Water Supply Chronic Standard 300

Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




* * * Historic Censored Data

Aquatic Life Acute Standard 281
Aquatic Life Chronic Standard 10.9

Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




○ ○ ○ Historic Data

Aquatic Life Acute Standard 4,738
Aquatic Life Chronic Standard 2,618

Figure 9. Distribution of selected water-quality constituents relative to time for


Montrose Arroyo at East Niagara Street, station 382802107513301.



○ ○ ○ Historic Data

Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




* * * Historic Censored Data

Aquatic Life Acute Standard 564
Aquatic Life Chronic Standard 428

Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.




* * * Historic Censored Data

Aquatic Life Acute Standard 340

Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.



○ ○ ○ Historic Data

Figure 9. Distribution of selected water-quality constituents relative to time for

Montrose Arroyo at East Niagara Street, station 382802107513301.

